



Vehicle History Report

Date Generated: 06-03-2026

[Copy Link](#) / [Download](#)



1955 Studebaker President Series 6H

VIN: 6I00659

Scan to open report:



Standard Specifications

Basic Info

Year: 1955
Make: Studebaker
Model: President

Performance

Engine: V8, Valve-in-head, Downdraft 4-barrel, Helical
Transmission: Automatic
Fuel: Regular

Body

Drive: Rear wheel drive
Doors: 4

Body

Body Maker: Studebaker
Passengers: 6
Model Number: Y
Weight: 3,165lbs

Carburetor

Type: Downdraft 4-barrel
Make: Own

Other Systems Specifications

Exhaust System: Dual
Ignition System: Distributor and coil
Battery: 6 volt storage battery

Dimension

Wheelbase: 120.5 inches
Length: 206.25 inches
Width: 70.58 inches
Height: 60 inches
Front Tread: 56.7 inches
Rear Tread: 55.7 inches

Transmission

Type: Helical
No. Of Gears: 3

Cooling System

Radiator: Centrifugal pump with thermostat, Cellular
17.25 Quarts

Wheels, Rims & Tires

Wheel Type: Steel
Wheel Mfr: Studebaker
Wheel Size: 15 inch
Tire Type: Bias Ply
Tire Size: 7.1 x 15
Spare Location: Trunk

Engine

Type: V8, Valve-in-head
Displacement: 259.16 cu. in.
Cylinders: 8
Bore & Stroke: 3.5625 & 3.25 inches
Compression Ratio-Std: 7.0 to 1
Brake Horsepower: 180@4500
Rated Horsepower: 180 hp
Torque: 258@2800
Main Bearings: 5
Valve Lifters: Mechanical
Block Material: Cast Iron
Engine Numbers: Last letter in serial no.
Engine No. Location: On block near right side of distributor mounting.
Lubrication: Pressure to all bearings excluding wrist pin

Gear Ratios

1st: 2.57:1
2nd: 1.55:1
3rd: 1:1
Reverse: 3.48:1
Clutch Type: Single plate dry disc
Clutch Size: 10 inches
Axle Type: Semifloating
Differential Ratio: 3.92 to 1

Capacities

Fuel: 18 Gallons
Oil: 6 Quarts
Cooling System: Centrifugal pump with thermostat, 17.25 Quarts
Rear Differential: 3 Pints
Front Differential: Not applicable
Transfer Case: Not applicable
Classic Rating: Milestone Car

Suspension

Front: Independent coil springs
Rear: Longitudinal leaf spring
Steering Gear: Cam & lever or worm & roller

Brakes

Service: 4 wheel hydraulic drum
Front Size: 11 inches
Rear Size: 10 inches
Emergency: Rear service brakes
Size: 11 inches

VIN/ID

VIN/Serial no.: Starting 4Y87Z100001
VIN Description: Total Digits: 11
Digits 1: Model year
Digits 2: Assembly plant
Digits 3-4: Body style
Digits 5: Engine
Digits 6-11: Production number

Title History

This section contains the title history records of the vehicle

No Problems Found!

Accident Records

This section contains the accident records of the vehicle



No Problems Found!


Theft Records

This section contains details of theft(s) or stolen records

 No Problems Found!

Lien / Impound / Export Records

This section contains lien, impound, and export records of the vehicle

 No lien, impound, and export records found!

Junk / Salvage / Insurance Records

This section lists junk, salvage, and insurance records (if any)

 No Junk / Salvage / Insurance Records records found!


Salvage Auction Records

This section contain details of historical salvage auction listings

 No salvage auction records found!

Sale Records

This section contains details of historical sales listings of the vehicle

 No sale records found!

Title Checks

This section contains major checks for potential problems related to vehicles title

Flood damage?

 No problems Found

Fire damage?

 No problems Found

Hail damage?

 No problems Found

Salt water damage?

 No problems Found

Vandalism?

 No problems Found

Kit?

 No problems Found

Dismantled?

 No problems Found

Junk?

 No problems Found

Rebuilt?	<input checked="" type="checkbox"/>	No problems Found
Reconstructed?	<input checked="" type="checkbox"/>	No problems Found
Salvage: Damage or Not Specified?	<input checked="" type="checkbox"/>	No problems Found
Salvage: Stolen?	<input checked="" type="checkbox"/>	No problems Found
Salvage: Reasons Other Than Damage or Stolen?	<input checked="" type="checkbox"/>	No problems Found
Test Vehicle?	<input checked="" type="checkbox"/>	No problems Found
Refurbished?	<input checked="" type="checkbox"/>	No problems Found
Collision?	<input checked="" type="checkbox"/>	No problems Found
Salvage Retention?	<input checked="" type="checkbox"/>	No problems Found
Prior Taxi?	<input checked="" type="checkbox"/>	No problems Found
Prior Police?	<input checked="" type="checkbox"/>	No problems Found
Original Taxi?	<input checked="" type="checkbox"/>	No problems Found
Original Police?	<input checked="" type="checkbox"/>	No problems Found
Remanufactured?	<input checked="" type="checkbox"/>	No problems Found
Gray Market?	<input checked="" type="checkbox"/>	No problems Found
Warranty Return?	<input checked="" type="checkbox"/>	No problems Found
Antique?	<input checked="" type="checkbox"/>	No problems Found
Classic?	<input checked="" type="checkbox"/>	No problems Found
Agricultural Vehicle?	<input checked="" type="checkbox"/>	No problems Found
Logging Vehicle?	<input checked="" type="checkbox"/>	No problems Found
Street Rod?	<input checked="" type="checkbox"/>	No problems Found
Vehicle Contains Reissued VIN?	<input checked="" type="checkbox"/>	No problems Found
Replica?	<input checked="" type="checkbox"/>	No problems Found
Totaled?	<input checked="" type="checkbox"/>	No problems Found

Owner Retained?	<input checked="" type="checkbox"/>	No problems Found
Bond Posted?	<input checked="" type="checkbox"/>	No problems Found
Memorandum Copy?	<input checked="" type="checkbox"/>	No problems Found
Parts Only?	<input checked="" type="checkbox"/>	No problems Found
Recovered Theft?	<input checked="" type="checkbox"/>	No problems Found
Undisclosed Lien?	<input checked="" type="checkbox"/>	No problems Found
Prior Owner Retained?	<input checked="" type="checkbox"/>	No problems Found
Vehicle Non-conformity Uncorrected?	<input checked="" type="checkbox"/>	No problems Found
Vehicle Non-conformity Corrected?	<input checked="" type="checkbox"/>	No problems Found
Vehicle Safety Defect Uncorrected?	<input checked="" type="checkbox"/>	No problems Found
Vehicle Safety Defect Corrected?	<input checked="" type="checkbox"/>	No problems Found
VIN Replaced?	<input checked="" type="checkbox"/>	No problems Found
Gray Market: Non-compliant?	<input checked="" type="checkbox"/>	No problems Found
Gray Market: Compliant?	<input checked="" type="checkbox"/>	No problems Found
Manufacturer Buy Back?	<input checked="" type="checkbox"/>	No problems Found
Former Rental?	<input checked="" type="checkbox"/>	No problems Found
Disclosed Damage?	<input checked="" type="checkbox"/>	No problems Found
Prior Non-Repairable / Repaired?	<input checked="" type="checkbox"/>	No problems Found
Crushed?	<input checked="" type="checkbox"/>	No problems Found
Hazardous?	<input checked="" type="checkbox"/>	No problems Found
Export Only Vehicle?	<input checked="" type="checkbox"/>	No problems Found
Odometer: Actual?	<input checked="" type="checkbox"/>	No problems Found
Odometer: Not Actual?	<input checked="" type="checkbox"/>	No problems Found
Odometer: Tampering Verified?	<input checked="" type="checkbox"/>	No problems Found

Odometer: Exempt from Odometer Disclosure?

 No problems Found

Odometer: Exceeds Mechanical Limits?

 No problems Found

Odometer: May be Altered?

 No problems Found

Odometer: Replaced?

 No problems Found

Odometer: Reading at Time of Renewal?

 No problems Found

Odometer: Discrepancy?

 No problems Found

Title Record Discrepancy?

 No problems Found

Odometer: Exceeds Mechanical Limits Rectified?

 No problems Found

This Classic Decoder Report is based only on information acquirable by Classic Decoder as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Classic Decoder. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2026 [Classic Decoder](#). All Rights Reserved.