



Vehicle History Report

Date Generated: 04-11-2025

[Copy Link](#) / [Download](#)

VIN: CK4PXXK93333R

Scan to open report:



Standard Specifications

Body

Body Maker:	Ford
No. Doors:	2
Passengers:	2-4
Model Number:	
Weight:	

Dimension

Wheelbase:	112 inches
Length:	
Width:	
Height:	
Front Tread:	55 1/8 inches
Rear Tread:	56 inches

Engine

Type:	Own V8, L-head
Displacement:	221 cu. in.
Cylinders:	8
Bore & Stroke:	3 1/16 & 3 3/4 inches
Compression Ratio-Std:	6.3 to 1
Compression Ratio-Opt:	Not applicable
Brake Horsepower:	90@3800
Rated Horsepower:	300
Torque:	
Main Bearings:	3
Valve Lifters:	
Block Material:	
Engine Numbers:	
Engine No. Location:	Top of clutch housing, and top of left frame rail opposite steering gear.
Lubrication:	

Carburetor

Type:	Dual downdraft
Make:	Stromberg

Transmission 2 1/2 Pints

Type:	Helical
Drive:	Rear wheel drive
No. Of Gears:	3

Gear Ratios

1st:	2.82 to 1
2nd:	1.604 to 1
3rd:	1 to 1
4th:	Not applicable
5th:	Not applicable
Reverse:	3.383 to 1
Clutch Type:	Single plate
Clutch Size:	9 inches
Axle Type:	3/4 floating
Differential:	Spiral bevel
Differential Ratio:	4.11 to 1

Suspension

Front:	Transverse leaf springs
Rear:	Transverse leaf springs
Steering Gear:	Worm & sector

Brakes

Service:	Internal expanding on 4 wheels, mechanical
Front Size:	12 inches
Rear Size:	12 inches
Emergency:	Internal expanding on rear wheels
Size:	12 inches

Other Systems Specifications

Exhaust System:	
Ignition System:	Distributor and coil
Battery:	6 volt storage battery
Cooling System:	, 22 Quarts
Radiator:	Tubular
Fuel Type:	
Mileage:	

Wheels, Rims & Tires

Wheel Type:	Steel spoke
Wheel Mfr:	
Wheel Size:	
Tire Type:	
Tire Size:	5.5 x 17
Spare Location:	

Capacities

Fuel:	
Oil:	5 Quarts
Transmission:	2 1/2 Pints
Cooling System:	22 Quarts
Rear Differential:	2 1/4 Pints
Front Differential:	Not applicable
Transfer Case:	Not applicable
Classic Rating:	Not Rated

VIN/ID

VIN/Serial no.:	18-457,478 and up
VIN Description:	

Title History

This section contains the title history records of the vehicle



No Problems Found!

Accident Records


This section contains the accident records of the vehicle



No Problems Found!


Theft Records

This section contains details of theft(s) or stolen records

 No Problems Found!


Lien / Impound / Export Records

This section contains lien, impound, and export records of the vehicle

 No lien, impound, and export records found!


Junk / Salvage / Insurance Records

This section lists junk, salvage, and insurance records (if any)

 No Junk / Salvage / Insurance Records records found!

Salvage Auction Records

This section contain details of historical salvage auction listings

 No salvage auction records found!











Sale Records

This section contains details of historical sales listings of the vehicle

 No sale records found!

Title Checks

This section contains major checks for potential problems related to vehicles title

Flood damage?	 No problems Found
Fire damage?	 No problems Found
Hail damage?	 No problems Found
Salt water damage?	 No problems Found
Vandalism?	 No problems Found
Kit?	 No problems Found
Dismantled?	 No problems Found
Junk?	 No problems Found
Rebuilt?	 No problems Found
Reconstructed?	 No problems Found

Salvage: Damage or Not Specified?



No problems Found

Salvage: Stolen?



No problems Found

Salvage: Reasons Other Than Damage or Stolen?



No problems Found

Test Vehicle?



No problems Found

Refurbished?



No problems Found

Collision?



No problems Found

Salvage Retention?



No problems Found

Prior Taxi?



No problems Found

Prior Police?



No problems Found

Original Taxi?



No problems Found

Original Police?



No problems Found

Remanufactured?



No problems Found

Gray Market?



No problems Found

Warranty Return?



No problems Found

Antique?



No problems Found

Classic?



No problems Found

Agricultural Vehicle?



No problems Found

Logging Vehicle?



No problems Found

Street Rod?



No problems Found

Vehicle Contains Reissued VIN?



No problems Found

Replica?



No problems Found

Totaled?



No problems Found

Owner Retained?



No problems Found

Bond Posted?



No problems Found

Memorandum Copy?



No problems Found

Parts Only?



No problems Found

Recovered Theft?



No problems Found

Undisclosed Lien?



No problems Found

Prior Owner Retained?



No problems Found

Vehicle Non-conformity Uncorrected?



No problems Found

Vehicle Non-conformity Corrected?



No problems Found

Vehicle Safety Defect Uncorrected?



No problems Found

Vehicle Safety Defect Corrected?



No problems Found

VIN Replaced?



No problems Found

Gray Market: Non-compliant?



No problems Found

Gray Market: Compliant?



No problems Found

Manufacturer Buy Back?



No problems Found

Former Rental?



No problems Found

Disclosed Damage?



No problems Found

Prior Non-Repairable / Repaired?



No problems Found

Crushed?



No problems Found

Hazardous?



No problems Found

Export Only Vehicle?



No problems Found

Odometer: Actual?



No problems Found

Odometer: Not Actual?



No problems Found

Odometer: Tampering Verified?



No problems Found

Odometer: Exempt from Odometer Disclosure?









No problems Found

Odometer: Exceeds Mechanical Limits?



No problems Found

Odometer: May be Altered?	 No problems Found
Odometer: Replaced?	 No problems Found
Odometer: Reading at Time of Renewal?	 No problems Found
Odometer: Discrepancy?	 No problems Found
Odometer: Call Title Division?	 No problems Found
Odometer: Exceeds Mechanical Limits Rectified?	 No problems Found

This Classic Decoder Report is based only on information acquirable by Classic Decoder as at the time of generating this report. Note that other information about this vehicle, including problems and services, may not have been reported to Classic Decoder. You are strongly advised to use this report only as an additional but important tool, along with the vehicle inspection and test drive, to make an informed decision about the purchase of this vehicle. © 2022 [Classic Decoder](#). All Rights Reserved.